

Lead Roof Flashing

BPIR Declaration

Version: 2

Designated building product: Class 1

Declaration

Simx has provided this declaration to satisfy the provisions of Schedule 1(d) of the Building (Building Product Information Requirements) Regulations 2022.

Product/system

Name	Lead Roof Flashing
Identifier	DCT0190

Description

To be used where the extraction system requires venting through the roof.

Other products this is used in	DCT1095, DCT2325
--------------------------------	------------------

Scope of use

This product is suitable for use in residential housing including houses, townhouses, and apartments (subject to confirming the suitability of the diameter for building code compliance)

Conditions/limitations of use

Please refer to installation instructions for the product and the installation instructions for the kit or system it is used in for recommend conditions and limitations when installing.

Relevant building code clauses and contributions to compliance

B2 Durability: Performance B2.3.1 (b) 15 years

E2 External Moisture: Performance: E2.3.1

F2 Hazardous Building Materials: Performance F2.3.1

G4 Ventilation: Performance G4.3.3(a), G4.3.3(b), G4.3.3(c)

Supporting information

The following additional information supports the above statements:

Installation Manual	https://simx.co.nz/images/uploads/resources/PUB1309_2008_Roof_Cowl_Kits_Installation_Instructions.pdf
Maintenance requirements	Clean with a damp cloth

Contact details


Manufacture location	New Zealand
Legal and trading name of manufacturer	Simx Limited
Manufacturer address for service	1 Haliday Place Auckland 2013
Manufacturer website	https://simx.co.nz/
Manufacturer NZBN	9429036278121
Manufacturer email	sales@simx.co.nz
Manufacturer phone number	092591660

Responsible person

As the responsible person as set out in Regulation 3, I confirm that the information supplied in this declaration is based on information supplied to the company as well as the company's own processes and is therefore to the best of my knowledge, correct.

I can also confirm that Lead Roof Flashing is not subject to a warning on ban under [s26 of the Building Act](#).

Signed for and on behalf of **Simx**:

A handwritten signature in black ink that reads "D. G. Latimer". The letters are cursive and connected.

David Latimer
Technical Manager
November 2023

SIMX
1 Haliday Place Auckland 2013 New Zealand
092591660 | <https://simx.co.nz/>